

Site ID	Locational Identifier	Lead Gooseneck Currently Present?	Current Street Side Service Line Material	Was Street Side Service Line Material Ever Previously Lead?	Street Side Service Line Size	Street Side Service Line Install Date	Current Property Side Service Line Material	Property Side Service Line Size	Property Side Service Line Install Date	Building Type	Point-of-Entry or Point-of-Use Treatment Present?	Building Plumbing Material 1	Building Plumbing Material 2	Building Plumbing Material Install Date	Comments	Basis of Street Side Material Classification	Was Street Side Material Field Verified?	Date of Street Side Field Verification, if Applicable	Method of Street Side Field Verification, if Applicable	Basis of Property Side Material Classification	Was Property Side Material Field Verified?	Date of Property Side Field Verification, if Applicable	Method of Property Side Field Verification, if Applicable	Notes on Basis of Material Classification
AH	W5679 Co F	N	C	N	1"		G	1"		SF	N	UNK				Installation record	N			Field inspection only	Y	04/26/2021	/visual insp at meter	
	4670 Co F	N	C	N	1"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	05/03/2021	/visual insp at meter	
	W5717 Bliss Rd	N	C	N	1"		C	1"		NONRES	N	C				Installation record	N			Field inspection only		07/29/2021	/visual insp at meter	
	N2129 Briarwood	N	C	N	1"		P	1"		SF	Y	O				Installation record	N			Field inspection only	Y	05/24/2021	/visual insp at meter	
	N2145 Briarwood	N	C	N	1"		P	1"		SF	Y	O				Installation record	N			Field inspection only	Y	04/26/2021	/visual insp at meter	
	N2161 Briarwood	N	C	N	1"		P	1"		SF	Y	O				Installation record	N			Field inspection only	Y	04/26/2021	/visual insp at meter	
	N2173 Briarwood	N	C	N	1"		P	1"		SF	Y	O				Installation record	N			Field inspection only	Y	07/21/2021	/visual insp at meter	
	N2180 Briarwood	N	C	N	1"		C	1"		SF	Y	C				Installation record	N			Field inspection only	Y	07/22/2021	/visual insp at meter	
	N2186 Briarwood	N	C	N	1"		P	1"		SF	Y	O				Installation record	N			Field inspection only	Y	05/11/2021	/visual insp at meter	
	N2198 Briarwood	N	C	N	1"		P	1"		SF	Y	O				Installation record	N			Field inspection only	Y	04/03/2024	/visual insp at meter	
	N2219 Briarwood	N	C	N	1"		C	1"		SF	Y	C				Installation record	N			Field inspection only	Y	09/01/2021	/visual insp at meter	
	N2235 Briarwood	N	C	N	1"		P	1"		SF	Y	O				Installation record	N			Field inspection only	Y	02/16/2022	/visual insp at meter	
	N2244 briarwood	N	C	N	1"		P	1"		SF	Y	O				Installation record	N			Field inspection only	Y	08/04/2021	/visual insp at meter	
	N2247 Briarwood	N	C	N	1"		C	1"		SF	Y	C				Installation record	N			Field inspection only	Y	04/22/2021	/visual insp at meter	
	N2256 Briarwood	N	C	N	1"		P	1"		SF	Y	O				Installation record	N			Field inspection only	Y	08/09/2021	/visual insp at meter	
	N2268 Briarwood	N	C	N	1"		P	1"		SF	Y	O				Installation record	N			Field inspection only	Y	08/09/2022	/visual insp at meter	
	N2284 Briarwood	N	C	N	1"		C	1"		SF	Y	C				Installation record	N			Field inspection only	Y	03/28/2024	/visual insp at meter	
	N2291 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	07/28/2022	/visual insp at meter	
	N2300 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	04/10/2023	/visual insp at meter	
	N2306 Briarwood	N	C	N	3/4"		P	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	08/09/2021	/visual insp at meter	
	N2314 Briarwood	N	C	N	3/4"		P	1"		SF	Y	O				Installation record	N			Field inspection only	Y	08/10/2021	/visual insp at meter	
	N2322 Briarwood	N	C	N	3/4"		P	1"		SF	N	C				Installation record	N			Field inspection only	Y	05/10/2021	/visual insp at meter	
	N2325 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	05/04/2021	/visual insp at meter	
	N2328 Briarwood	N	C	N	3/4"		P	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	07/28/2021	/visual insp at meter	
	N2337 Briarwood	N	C	N	3/4"		C	1"		SF	Y	C				Installation record	N			Field inspection only	Y	05/05/2021	/visual insp at meter	
	N2340 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	05/03/2021	/visual insp at meter	
	N2341 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	O				Installation record	N			Field inspection only	Y	05/03/2021	/visual insp at meter	
	N2346 Briarwood	N	C	N	3/4"		P	1"		SF	Y	C				Installation record	N			Field inspection only	Y	05/03/2021	/visual insp at meter	
	N2353 Briarwood	N	C	N	3/4"		C	1"		SF	Y	C				Installation record	N			Field inspection only	Y	07/27/2021	/visual insp at meter	
	N2354 Briarwood	N	C	N	3/4"		C	1"		SF	Y	C				Installation record	N			Field inspection only	Y	05/03/2021	/visual insp at meter	
	N2360 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	07/22/2021	/visual insp at meter	
	N2368 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	04/26/2021	/visual insp at meter	
	N2369 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	05/04/2021	/visual insp at meter	
	N2372 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	08/30/2021	/visual insp at meter	
	N2377 Briarwood	N	C	N	3/4"		P	1"		SF	Y	C				Installation record	N			Field inspection only	Y	09/01/2021	/visual insp at meter	
	N2380 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	05/13/2021	/visual insp at meter	
	N2385 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	05/10/2021	/visual insp at meter	
	N2391 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	08/09/2021	/visual insp at meter	
	N2402 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	04/29/2021	/visual insp at meter	
	N2411 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	08/04/2021	/visual insp at meter	
	N2418 briarwood	N	C	N	3/4"		P	1"		SF	Y	O				Installation record	N			Field inspection only	Y	04/28/2021	/visual insp at meter	
	N2445 Briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	05/03/2021	/visual insp at meter	
	N2457 briarwood	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	07/27/2021	/visual insp at meter	
	N2295 FenLockney	N	C	N	1"		G	1"		SF	Y	C				Installation record	N			Field inspection only	Y	05/12/2022	/visual insp at meter	
	N2303 FenLockney	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	04/22/2021	/visual insp at meter	
	N2309 FenLockney	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	08/09/2021	/visual insp at meter	
	N2317 FenLockney	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	05/05/2021	/visual insp at meter	
	N2318 FenLockney	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	04/28/2021	/visual insp at meter	
	N2321 FenLockney	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	08/04/2021	/visual insp at meter	
	N2322 FenLockney	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	08/10/2021	/visual insp at meter	
	N2326 Fenlockney	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	08/05/2021	/visual insp at meter	
	N2333 FenLockney	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	02/16/2021	/visual insp at meter	
	N2339 FenLockney	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	07/28/2021	/visual insp at meter	
	N2340 FenLockney	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	09/02/2021	/visual insp at meter	
	N2347 FenLockney	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	08/31/2021	/visual insp at meter	
	N2350 FenLockney	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	04/28/2021	/visual insp at meter	
	N2353 FenLockney	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	07/26/2021	/visual insp at meter	
	N2355 fenLockney	N	C	N	3/4"		P	1"		SF	Y	C				Installation record	N			Field inspection only	Y	04/26/2021	/visual insp at meter	
	W5719 Heatherwoo	N	C	N	3/4"		C	1"		SF	Y	C				Installation record	N			Field inspection only	Y	04/22/2021	/visual insp at meter	
	W5720 Heatherwoo	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	08/31/2021	/visual insp at meter	
	W5725 Heatherwoo	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	05/26/2021	/visual insp at meter	
	W5726 Heatherwoo	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	08/03/2021	/visual insp at meter	
	W5731 Heatherwoo	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	05/06/2021	/visual insp at meter	
	W5732 Heatherwoo	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	05/04/2021	/visual insp at meter	
	W5749 Heatherwoo	N	C	N	3/4"		C	1"		SF	Y	C				Installation record	N			Field inspection only	Y	07/20/2021	/visual insp at meter	
	W5720 Thistledown	N	C	N	3/4"		C	1"		SF	Y	C				Installation record	N			Field inspection only	Y	08/08/2021	/visual insp at meter	
	W5728 Thistledown	N	C	N	3/4"		P	1"		SF	Y	C				Installation record	N			Field inspection only	Y	05/12/2021	/visual insp at meter	
	W5734 Thistledown	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	07/21/2021	/visual insp at meter	
	W5735 Thistledown	N	C	N	3/4"		P	1"		SF	Y	C				Installation record	N			Field inspection only	Y	05/04/2021	/visual insp at meter	
	W5743 Thistledown	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	03/25/2024	/visual insp at meter	
	W5749 Thistledown	N	C	N	3/4"		C	1"		SF	Y	C				Installation record	N			Field inspection only	Y	04/28/2021	/visual insp at meter	
	W5752 Thistledown	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	07/20/2021	/visual insp at meter	
	W5753 Thistledown	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	05/03/2021	/visual insp at meter	
	W5760 Thistledown	N	C	N	3/4"		C	3/4"		SF	Y	O				Installation record	N			Field inspection only	Y	02/21/2023	/visual insp at meter	
	W5761 Thistledown	N	C	N	3/4"		P	1"		SF	Y	C				Installation record	N			Field inspection only	Y	05/10/2022	/visual insp at meter	
	W5767 Thistledown	N	C	N	3/4"		C	1"		SF	Y	C				Installation record	N			Field inspection only	Y	04/22/2021	/visual insp at meter	
	W5768 Thistledown	N	C	N	3/4"		P	3/4"		SF	Y	C				Installation record	N			Field inspection only	Y	05/05/2021	/visual insp at meter	
	W5774 Thistledown	N	C	N	3/4"		C	3/4"		SF	Y	C				Installation record	N			Field inspection				

